

GSX-R1000召回車輛 (尚未回廠檢修明細)

附件一

NO.	車體號碼	引擎號碼	機型
1	JS1GT76AX62112908	T713 -144706	GSX-R1000K6
2	JS1GT76AX62112911	T713 -144702	GSX-R1000K6
3	JS1GT76A462114265	T713 -146908	GSX-R1000K6
4	JS1GT76AX62114268	T713 -146905	GSX-R1000K6
5	JS1GT76A162114269	T713 -146904	GSX-R1000K6
6	JS1GT76AX62115193	T713 -148601	GSX-R1000K6
7	JS1GT76A562115196	T713 -148598	GSX-R1000K6
8	JS1GT76A462116159	T713 -150558	GSX-R1000K6
9	JS1GT76A162116166	T713 -150551	GSX-R1000K6
10	JS1GT76A362116167	T713 -150550	GSX-R1000K6
11	JS1GT76A562116171	T713 -150546	GSX-R1000K6
12	JS1GT76A062116188	T713 -150565	GSX-R1000K6
13	JS1GT76A062116191	T713 -150562	GSX-R1000K6
14	JS1GT76A462116193	T713 -150560	GSX-R1000K6
15	JS1GT76A762116205	T713 -150572	GSX-R1000K6
16	JS1GT76A662116275	T713 -150646	GSX-R1000K6
17	JS1GT76AX62116277	T713 -150644	GSX-R1000K6
18	JS1GT76A262116287	T713 -150658	GSX-R1000K6
19	JS1GT76A662116289	T713 -150656	GSX-R1000K6
20	JS1GT76A462116291	T713 -150678	GSX-R1000K6
21	JS1GT76A662116292	T713 -150677	GSX-R1000K6
22	JS1GT76A862116293	T713 -150676	GSX-R1000K6
23	JS1GT76AX62116294	T713 -150675	GSX-R1000K6
24	JS1GT76A562116297	T713 -150672	GSX-R1000K6
25	JS1GT76A162116300	T713 -150669	GSX-R1000K6
26	JS1GT76A562116302	T713 -150691	GSX-R1000K6
27	JS1GT76A962116304	T713 -150689	GSX-R1000K6

NO.	車體號碼	引擎號碼	機型
1	JS1GT77A672103994	T715 -108518	GSX-R1000K7
2	JS1GT77A872104354	T715 -108766	GSX-R1000K7
3	JS1GT77AX72104355	T715 -108765	GSX-R1000K7
4	JS1GT77A772104359	T715 -108761	GSX-R1000K7
5	JS1GT77AX72104694	T715 -109138	GSX-R1000K7
6	JS1GT77A372104701	T715 -109131	GSX-R1000K7
7	JS1GT77AX72109085	T715 -118771	GSX-R1000K7
8	JS1GT77A372109087	T715 -118784	GSX-R1000K7
9	JS1GT77A572109088	T715 -118783	GSX-R1000K7
10	JS1GT77A072109094	T715 -118777	GSX-R1000K7
11	JS1GT77A272109095	T715 -118775	GSX-R1000K7

※以上統計至 2015年 12月 18日止